

LITTLE ILFORD AREA **BEFORE AND AFTER TRAFFIC DATA**

ONE WAY SYSTEM

(%)

Traffic Survey Location	Before	After	%
Romford Road near Dersingham Avenue (Eastbound)	9808	10106	3%
Romford Road near Dersingham Avenue (Westbound)	10593	10333	-2%
Romford Road near Eight Avenue (Eastbound)	6900	7405	7%
Romford Road near Eight Avenue (Westbound)	8369	8564	2%
Romford Road near Fifth Avenue (Eastbound)	7580	8083	7%
Romford Road near Fifth Avenue (Westbound)	7129	7804	9%
Romford Road near Greenhill Grove (Eastbound)	5057	5227	3%
Romford Road near Greenhill Grove (Westbound)	6650	6975	5%
High Street North (Northbound)	3470	3557	3%
High Street North (Southbound)	3714	4084	10%
Fourth Avenue	2411	1645	-32%
Little Ilford Lane	3284	3071	-6%
Dersingham Avenue	3622	2874	-21%



% INCREASED TRAFFIC TOWARDS POINTED DIRECTION % DECREASED TRAFFIC TOWARDS POINTED DIRECTION

Collected on: 08-10/2019 Collected on: 10/2020 (7am -7pm) (7am-7pm)



